

MULTI-FUNCTION LCD WEATHER CLOCK

FEATURES:

Measuring temperature range: 0°C- 50°C (32°F - 122°F)

Measuring humidity range: 20%-99%

Resolution: 1°C

Display: Max / Min temperature and humidity records

Calendar range: 2001-2099

OPERATION:

Press mode once to view the calendar.

Press mode once again to view the alarm time.

SETTING THE TIME:

1. Press and hold MODE for 3 seconds to enter the time setting mode.
2. The hour digits will start blinking and can be set by pressing UP or Down.
3. Press MODE until the minute digits start blinking. This can be set by pressing UP or DOWN.
4. Press MODE again.

SETTING THE ALARM:

1. Press MODE twice to view the alarm time.
2. Press and hold MODE for 3 seconds to enter the alarm setting mode.
3. The hour digits will start blinking and can be set by pressing UP or DOWN.
4. Press MODE and the minute digits start blinking. This can be set by pressing UP or DOWN.
5. Press MODE again.

SWITCHING ALARM ON/OFF:

Press Up to switch the alarm on/off. A Bell will appear beside the time when the alarm is on.

SETTING THE CALENDAR:

1. Press MODE once to view the calendar.
2. Press and hold MODE for 3 seconds to enter the calendar setting mode.
3. The Year appears blinking and can be set by pressing UP or DOWN.
4. Press the MODE and the month digits start blinking. This can be set by pressing UP or DOWN.
5. Press the MODE and the day digits start blinking. This can be set by pressing UP or DOWN.
6. Press MODE again.

MAX/MIN

Press MAX/MIN to view the maximum temperature and humidity record.

Press MAX/MIN again to view the minimum temperature and humidity record.

12/24 HOUR FORMAT

In time mode, press and hold UP for 3 seconds to switch to 12 or 24 hour format display.

°C / °F TEMPERATURE FORMAT

Press DOWN to switch to °C / °F temperature display.





SNOOZE

When the alarm sounds press SNZ to enter snooze mode.

WEATHER FORECAST

TEMPERATURE RANGE

< 59° F (15° C) 60.8° F - 77° F
(15° C - 125° C) >78.8° F (26° C)

	< 59° F (15° C)	60.8° F - 77° F (15° C - 125° C)	>78.8° F (26° C)	
 SUNNY	<40%	<55%	<60%	HUMIDITY RANGE
 PARTLY CLOUDY	41%- 65%	56%-70%	61%-75%	
 CLOUDY	66%- 71%	71%- 79%	76%- 86%	
 RAIN	>71%	>79%	>86%	

COMFORT LEVEL



TEMPERATURE: 20°C - 25°C
HUMIDITY: 40% - 70%



TEMPERATURE: ANY TEMPERATURE
HUMIDITY: <40%



TEMPERATURE: ANY TEMPERATURE
HUMIDITY: >70%

NO DISPLAY

TEMPERATURE: NOT BETWEEN 20°C - 25°C
HUMIDITY: 40% - 70%